

WEEKLY QUALITY ASSURANCE REPORT

PAGE ____

OF ____

Name of Contractor: Global Engineering

Project Name: Life Safety--Walls Phase 2

Installation Name: Fort Gordon, GA, USA

Contract/DO/PO Number: 24-128

Contract Number: DACA01-98-D-0024

Date: week ending December 21, 2000

(USE SEPARATE REPORT FOR Each D.O./P.O. / Contract)

General Comments:

.

Work performed:

Replaced ceiling grid on the 7th 8th and 9th floors
Painted ceiling grid on the 7th and 8th floors.
Replaced ceiling tile on the 9th floor
Replaced exit lights on the 8th and 9th floors.

Percent complete (if applicable) 30 %

.

Safety violations / Corrective measures taken:

Safety meeting held

Work Scheduled:**Indicate Attachments:**

% Daily QA Reports

% Schedule assessments

% Inspection Checklist

% Other

% Safety Tool Box Meeting

% Minutes of Meetings

% Assistance provided to Facility

Manager

Name: Lloyd South

(Printed)

US Army Corps of Engineers
Quality Assurance Representative
Supporting MedCom

Signature: Lloyd South